

Full Side Awning Center Support

Was caught by our by a “Wind Devil” while crossing New Mexico, the wind caught the front of the Awning and snapped the center guide support off. Called Fleetwood about obtaining another center bracket, they told me that the part would be a production again for another year.

So I had no other choice but to manufacture a center bracket that of some scrap steel I acquired from Ace Hardware, now six months and 15,000 miles later, it's still there and working fine.